## Addendum # 2 06/10/14

All properties located within the EPA's Superfund Zone shall be subject to the following:

Wrecking contractor follow and required to adhere to any and all requirements and/or regulations imposed by this agency. Contact information is as follows:

Michael Berkoff, Remedial Project Manager U.S. EPA Region 5 - Superfund Division Remedial Response Section #3 Phone:(312) 353-8983 Fax:(312) 582-5160

- 1. Demolish and remove entire building structures including any and all sub-structures such as foundations, basement walls, basement flooring and footings, fencing, assessor structures, etc.
- 2. Lot shall be cleaned and cleared of all rubbish and debris accumulated in the course of abatement and graded.
- 3. Contractor required to follow the health and safety plan attached to the Weaver Boos plan when they are excavating soil around foundations, etc.
  - Note the worker personal protective equipment and dust control instructions as they are particularly important during excavation work.
- 4. Any and all foundations, walls, etc. demolished and/or removed are required to be decontaminated before it is disposed of without restrictions.
- 5. All excavated soil required to be disposed of as contaminated soil, which excavation shall be backfilled and covered with clean soil (sand) and clean top soil.
  - All excavated soil required to be disposed of as contaminated soil, including 4'x2' buffer running parallel to structure.
  - All excavated soil 2' in depth from ground level exposing native sand, to be disposed of as contaminated soil.
  - Fill cavity with clean fill (sand), compact to prevent settling and top soil.
- 6. Assure that proper ground covering is in place to prevent disturbance of existing soil.
  - All equipment that comes in contact with the contaminated soil must be decontaminated at the property and in accordance with the Weaver Boos Plan.

## 7. General

- All above ground demolished materials shall be disposed of offsite.
- All demolished debris to be decontaminated prior to removal/disposal.
- Mobil equipment, etc. ground barrier to be in place to prevent disturbance of existing soil.
- Release of liability to be executed prior to issuance of wrecking permit.
- 6' chain link fence structure to be erected around perimeter of site prior to commencement of work, including visible no trespassing/danger signs attached to each side of fence structure.
- Contractor shall commence demolition immediately upon meeting any and all requirements imposed, and shall complete said work within the specified time period from receipt of the notice to proceed.

- The lot, including public ways, shall be left cleaned of all rubbish at the conclusion of the project whether rubbish is affiliated with demolition of the structures or not.
- Assure all work is done in compliance with all environmental, health and safety codes and regulations, including any and all local and State requirements.
- Contractor to coordinate start date of demolition with Building Department and EPA.
  - a. Representative of EPA to be present during demolition to assure proper precautionary measures, applicable requirements, etc. are followed.
  - b. Contractor required to meet and follow any and all health and safety plans in place.
- Wrecking permit to be acquired from Building Department prior to commencement of demolition work.
  - a. IDEM notifications required to be submitted by contractor (if applicable).
  - b. Verification of termination of services/utilities (water, NIPSCO, etc.) required.
- Rodent control receipts required to be submitted.
- Public right of way permits required to be applied for with the East Chicago Engineering Department.
- Source and type of clean fill.
  - a. Receipts required to be submitted prior to claim being submitted for payment.
- Disposal facility information.
  - a. Dump receipts required prior to claim being submitted for payment.